## **BUILDING SAFETY CERTIFICATE**

No. 862 Dated: 23-05-2025

It is certified that the existing building of Sardar Chetan Singh Sarvhitkari Sr. Sec. Vidya Mandir, Mansa at Near Bhagat Singh Circle, Jagdambey Road, City: Mansa, Tehsil and District: Mansa (Punjab) is having block(s)/Floor(s) as per details below:

| Detail of Block<br>(s) in School | Block (1) | Block (2) | Block(3) | Block (4) |
|----------------------------------|-----------|-----------|----------|-----------|
| Number of floors in the block    | 3         | 3         | •        | -         |

The building is owned/occupied by Sardar Chetan Singh Sarvhitkari Sr. Sec. Vidya Mandir, Mansa running under Vidya Bharti Educational Trust, Mansa have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Sub Divisional Engineer, Sub Division No. 1, PWD, Mansa, (Punjab) on 16-05-2025 in the presence of Assistant Engineer, PWD, Mansa and that the building/premises is fit for occupancy for running school with effect from 01-04-2025 for a period of one year (up-to 31-03-2026) in accordance with rule and subject to compliance of the specific conditions as appended.

- The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing Capacity, Foundation details, structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
- In case any addition, alteration, expansion and modification to this building are required/ to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
- 3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. Immediately inspection of the undersigned arranged to check the stability and safety of the building.
- A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- A separate certificate regarding Electrical works should be obtained from the competent Authority.
- 6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.

S. Chetan Single Sarvhitkari Sr. Sec Vidya Mandir Mansa S. Chetan Singh Sarvhitkari Sr. Sec. Vidya Mandir, Mansa (Affi. to C.B.S.E) Affi. No. 1630927 School Code: 20916

- 7. This report is for the covered area of the school building . 7.4.7.9.1.39 .... which is submitted by the owner of the school building as per drawing.
- 8. The building of the school is constructed as framed structure/brick masonry.
- 9. This report is not valid for legal purpose.
- 10. That the fee charges for the year 2025-26.

Issued on 23.05.2025 at Mansa. by

Provi Div PWD BAR Br.

Signature with Seal

Executive Engineer Designation

Name & Address of Department/ Office

S. Chetan Single Sarvhitkari Sr. Sec Vidya Mandir Mansa

5. Chetan Singh Sarvhitkofi Sr. Vidva Mandir, Maksa (Affi. to C.B.S.E) Affi. No. 1630927

School Code: 20916

## **Building Safety Report**

NAME OF SCHOOL: S. Cheton Singh saryhitter's on scurvidge mandis

(District-MANSA)

As per report of Assistant/ Junior Engineer on his visually inspection on dated 16-5-25 the above mentioned school seems visually safe subject to the following observations and conditions.

- The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing Capacity, Foundation details, structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
- In case any addition, alteration, expansion and modification to this building are required/ to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
- In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. Immediately inspection of the undersigned arranged to check the stability and safety of the building.
- A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- A separate certificate regarding Electrical works should be obtained from the competent Authority.
- 6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
- 7. This report is for the covered area of the school building 716791P which is submitted by the owner of the school building as per drawing.
- 8. The building of the school is constructed as framed structure/ brick masonry.
- 9. This report is not valid for legal purpose.
- 10. That the fee charges for the year 2015 16

As per visually inspection as reported by the concerned Assistant/ Junior Engineer the above building may be used for normal use for One year up to 31 -03 - 14 subject to the above conditions.

Assistant/ Junior Engineer

President

S. Chetan Single Sarvhitkari Sr. Sec Vidva Mandir Mansa ਪ੍ਰਿੰਘ ਮੰਤਰ ਇੰਜੀਨੀਅਰ ਪ੍ਰਤਿਕ ਉਪ ਮੰਤਰ ਨੂੰ 1 ਲੋ.ਨਿ.ਵਿ.

(ਤ ਤੇ ਮ) ਜ਼ਾਬਾ, ਮਾਨਸਾ

S. Chetan Singh Sarvhitkari Sr. Sec. Vidya Mandir, Mansa (Affi, to C.B.S.E) Affi. No. 1630927

School Code: 20916

•